M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225501

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of work :→ Improvements of RCC drain and covering Slab Dasarhalli Metro station to. Byrappa circle Right side ward. No. 15 T. Dasarhalli EST Cost : 75.00 Lakhs P-code No. P-3518 Job code : 015-19-000003 Administrative Appvd : EE/DD/AS/68/19-20, Dt : 17/06/2019 Technical Sanction : CE/DZ/TS/46/19-20, Dt : 24/06/2019 Agency : Technical Manager ~~KRIDL~~ KRIDL						

W.O No :- BBMP/EE/DD/NO/358/2019-20 Dt 28/06/19

Scanned with CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Abstract As Per EMB						
(1)	Of Items Description		Unit	Qnty	Rate	Amt.	
(1)	Dismtling		Cum.	265.44	1684.34	447091.00	
(2)	Earth work Excavation		-11-	893.98	189.74	169624.00	
(3)	Providing ccm 1:3:6		-11-	111.75	5421.90	605884.00	
(4)	Providing ccm M20		-11-	300.83	7079.20	2126927.00	
(5)	Supplying and fixing Pre Cast RCC Slab		Sq/m	552.98	2208.00	1220975.00	
(6)							

Scanned with CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

Serial No. 225502

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions			Contents	Reference to last Measurement
			Length	Breadth	Depth		
1	2						8
(6)	T.M.T/ Fe-500		Tonne.	19.80	7232.68	1432074.00	
(7)	Pre cast slab of 250 mm thickness		Sqm.	62.55	524.00	32782.00	
(8)	Disposal of debris		Cum.	789.00	69.80	55072.00	
					Total:	6385472.00	
					GST 12%	766257.00	
					KRIDL 4.5%	287346.00	

Grand Total : 7439075.00

ದಾಖಲೆ ಪರಿಶೀಲಿಸಿದೆ. 30/12/20.

ದಾಪರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ

ಬಾಗೇಪಲ್ಲಿ. ಜಿ.ಐ.ಎಂ.ಪಿ.

Scanned with CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

CERTIFICATE

(1) This is to certify that the contractor has complet
the work satisfa

(2) The contractor has cleared the debris from the work spot

(3) The contractor has used his own vehicles for the carrying
the disma

(4) There are no departmental issues for the above work.

AE

3/11/20.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪಾಲಿಕೆ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಬಾಣಸವಾಡಿ, ಪೂರ್ವ ವಿಭಾಗ
ಬೆಂಗಳೂರು-560043



Scanned with CamScanner

Reference to last Measurement 8
ctor has completed the work satisfactorily n the work spent or the covering the dishonest bove work. ube station
119.30 — 42.30

M. A. R. 57 (Rule 116) **No. D** 225503

Measurement Book

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
						65.70M	
						mahishoodi Nagara 1st Cro.	
						125.70M	
	Dasarahalli 1st main road.						
	1st Cross 26.50						
	2nd Cross 26.30						
	3rd Cross 27.60M						
	4th Cross	50.50M					
	5th Cross		lengthy Culvert. 21.00M	3.50		6.30M Culvert.	
	6th Cross					91.00M	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ

Mahishoodi Amma Temple Road

Scanned with CamScanner